

DYNO LOGIC REPAIRS

Information sheet

Date: 19/06/08

Customer Willem Grimsell

Vehicle Toyota Hilux 2.7 Unichip

Model SAC 2004

Reg. no. _____

Telephone _____

Kilometres 54 629

Airportweg 388

Doornpoort

Schalk

082-880-6116

012-5471111

Speed
 Dyno 120 Km/h
 +/- 25 hp, @14.6 Afr
 Speedo 129 Km/h
 Over 7.50%
 At flywheel

RPM	Before Hp	Afr	After KW	After Hp	Afr	Aft Torque	Hp	Kw	Nm	Notes
1000			17.5	23.4	13.4	166.6	35.10	26.3	249.94	
1500			26.9	36.1	13.8	171.4	54.15	40.6	257.06	
2000			39.4	52.8	13.8	188.0	79.20	59.4	281.98	
2500			49.2	66.0	14.0	188.0	99.00	74.3	281.98	
3000			57.6	77.2	13.2	183.2	115.80	86.9	274.86	
3500			67.7	90.8	13.8	184.7	136.20	102.2	277.10	
4000			77.9	104.5	13.4	186.0	156.75	117.6	279.04	
4500			86.5	116.0	13.4	183.6	174.00	130.5	275.33	
5000			88.4	118.6	14.1	168.9	177.90	133.4	253.35	
5500			82.0	110.0	13.8	142.4	165.00	123.8	213.62	

100.00 % Verbetering Hp + Torque

Jets: Std: Mod: Valves:

CRUISE CO. 1ste:

Start @ 3000 Rpm Final @ 3000 Pwr:

Vac Bef hp Bef Afr Aft hp Aft Afr 2de: Comments

16'					Type:	Ign.	
14'						Timing	
12'					Venturi's	Was:	
10'						Now:	
8'							
6'					Pwr valve		
4'					2nd Choke	Plug Gap	
2'					areas		

